
From: The Stewards
To: Bryan Herta Autosport Car No 33 Delgado
Re: Request for Wheel speed sensor


Stewards Decision No. TC 01
Date: September 22, 2022
Time: 07:40:29

The competitor has requested permission (RQ SB TC 01) to compete with the rear left wheel speed sensor disconnected. The competitor reports that they are working with the manufacturer to resolve an issue, but the immediate solution is to disconnect one of the rear wheel speed sensors.

The Series Technical Manager has been consulted and agrees to this solution. After considering the matter, the stewards grant a one-event waiver to allow the competitor to disconnect a single rear wheel speed sensor.



Robert Davis (chairman)



John Walsh



Peter Cunningham

Acknowledgement of Receipt:

Time:

Date: